

Bulletin No.: 01-07-30-032D

Date: October 30, 2006

TECHNICAL

Subject:

Transmission Oil Leaking From Transmission Vent (Replace Transmission Case Cover (Channel Plate) Gasket)

Models:

1997-2007 GM Passenger Cars and Light Duty Trucks (including Saturn)

with Hydra-Matic 4T65-E Automatic Transmission (RPOs MN3, MN7, M15, M76)

Supersede:

This bulletin is being revised to update the correction information. Please discard Corporate Bulletin Number 01-07-30-032C (Section 07 - Transmission/Transaxle).

Condition

Some customers may comment on a transmission oil leak.

Cause

This condition may be caused by an improperly torqued channel plate gasket.